Nov 29, 1979

Stu Haigh
1557 Warbler Way
Sunnyvale CA 94087

H: Bob.

Well my Bally "Computer" is no longer working and I've gotten a 2 to 6 week time-to-fix quote from Alco.

I installed the 'Clock Fix' and had hoped to do a complete write up on it. However, my unit decided to 'Give up the ~~Ghost~~ Ghost'.

The only things I can tell you about the Clock Fix are:

1. Once installed you can no longer cover, and therefore inclose, the Oscillator Section. This will cause the unit to radiate. This in turn may or may not be harmful to your TV picture, (may inject noise).

2- The Fix improved the edge of the clocks so that any CMOS device should like them.

3- After I installed the 'Fix' my unit ~~no~~ would no longer work. I don't believe this was due to the Fix.

I am at the point now where I've set the Bally to one side and am very unhappy with it.

I've inclose a check for #15.00 to cover the manual I got from you.

I am at the point now where I think I give up on the Bally as my primary computer and instead i'll use it as a "intelligent" terminal for a new system that I am now designing.

Shalom
Stu Haig